

Jet-Trans


*A COLD PEEL Ink Jet Transfer Paper for Light Colored Fabrics.
Heat Press Recommended*



PRINTING INSTRUCTIONS

- ◆ **Print on the unlined side of the paper**
- ◆ **Print your image “mirrored”**
- ◆ **Select “Plain Paper” as your paper setting**
- ◆ **Select the following resolutions for your printer:**
 - **EPSON: 360 , 720, or “fine”**
 - **HP: Best**
 - **CANON: Standard**

Note: As printers and Inks vary, these settings are merely recommendations. It is important that a minimal amount of ink be used to assure that it penetrates the coating and comes out of your printer “DRY”. Excessive ink will result in running and bleeding of colors especially in the wash.



TRANSFERRING YOUR PRINT

- ◆ **Jet Trans can be used on Cotton, 50/50 and some other fabrics which are not overly “stretchy” and can withstand the recommended heat transfer temperatures.**
- ◆ **Always pre-press your fabric for 3-5 seconds to remove wrinkles and excess moisture.**
- ◆ **Trim your transfer to avoid transferring excess film coating around the image.**
- ◆ **Place the transfer “image side down” on the substrate.**
- ◆ **Press for 20-30 seconds at 350 degrees using Medium / Heavy pressure.**
- ◆ **After opening the press, set the transferred item aside to COMPLETELY before peeling the paper backing off in a smooth motion.**

WASHING

*Turn the garment inside out, wash in **Cold** water using a **NON-BLEACH** detergent. Add **NO BLEACH**. Remove Immediately and **DRY**.*